Harris County Fresh Water Supply District 61 June 2021 - Operations Report

	W	ater Produ	ction		
<u>Facility</u>	Gallons		Daily Avg.		YTD Gallons
Barwood	5,232,000		174,400		25,222,000
Hastings Green	23,886,000		796,200		128,292,000
Huffmeister	14,924,000		497,467		60,579,000
Ravensway	16,062,000		535,400		116,390,000
Total	60,104,000		2,003,467		330,483,000
D			Month %		YTD %
Pumped to Billed	57,730,000	COV48 125	96%		94%
District 61 Connections (Actual - 4061)	8067 - SFE (2016 Proje	ction)			
248 (Actual – 697)	2164 - SFE		SFE's Purchase	d – 2,500	
Wastewater Treatment					
<u>Facility</u>	Gallons		Daily Avg.		YTD Gallons
Barwood	18,482,000		616,067		114,433,000
Hastings Green	61,051,000		2,035,033		352,220,000
Total	79,533,000		2,651,100		466,653,000
<u>Rainfall</u>	Month	8.6	Annual	36.1	,
Distribution and Collection					
20 Bacteriological samples were taken: No coliforms detected.					
	C				
PACK DECEMBER AND DECEMBER OF THE PACK	Current Month	<u>Annual</u>			
Meter change out program:	0	12			
Distribution line leaks:	3	21			
Residential Taps:	0	0			

Continuation of Fire Hydrant Maintenance and Manhole Repair Throughout the District.

Water Meter Replacement Project is Nearing Completion

Phase 7 & 9 Sanitary Sewer Rehab Project is Underway


Commercial Taps:

Out of District Use User **Current Month Allocated Annual Usage Emerald Forest** 235,000 1,050,000 2,186,000 **MUD 248** 13,120,000 26,250,000 64,305,000 MUD 69 0 **Emergency** 400,000 Timberlake UD 0 Emergency 0 **MUD 222** Emergency 0 13,355,000 Totals: 66,891,000

Personnel

July Safety Meeting on Lock Out/Tag Out Completed on 7.8.21

August Safety Meeting Will be on Proper Lifting & Preventing Back Injuries



> BARWOOD WWTP # 1

CFI - Performed annual flow meter calibration

> HASTINGS GREEN WWTP # 2

CFI – Performed annual flow meter calibration Loftin Equipment – Performed annual generator service EFS – Replaced timers on wasters

> BARWOOD WP # 1

N/A

> HASTINGS GREEN WP # 2

Fluid Meter – Pulled Fallbrook well meter, took to shop for repairs

> HUFFMEISTER WP # 3

N/A

> RAVENSWAY WP # 4

Corr-Pro – Performed annual inspection & testing of cathodic protection system

> OAK CLIFF LIFT STATION

N/A

BECK MASTEN LIFT STATION

N/A

> NEESHAW LIFT STATION

N/A

- > ELDRIDGE CROSSING LIFT STATION N/A
- ➤ WORTHAM LANDING LIFT STATION N/A
- > WORTHAM FALLS LIFT STATION N/A
- > RAVENSWAY LIFT STATION N/A
- > CROSSBEND VILLAGE LIFT STATION N/A
- > 248 HUFFMEISTER LIFT STATION N/A
- > 248 WHITE OAK FALLS LIFT STATION N/A
- **ELEVATED STORAGE TANK #2**

Corr-Pro – Performed annual inspection & testing of cathodic protection system